

Contents

(xii)

Contents

<i>Chapters</i>	<i>Pages</i>
1. ENGINEERING MATERIALS AND RECENT ADVANCES	1—25
1.1 Historical Perspective of Materials	1
1.1.1 Modern Perspective of Materials	1
1.2 Materials Science and Engineering Materials	1
1.2.1 Importance of Materials Science in Inter-Disciplinary Subjects	2
1.3 Different Types of Engineering Materials	2
1.3.1 Metals	2
1.3.2 Non-Ferrous Metals	3
1.3.3 Ceramics	3
1.3.4 Organic Polymers	3
1.3.5 Alloys	4
1.3.6 Composites	4
1.3.7 Classified Group of Materials, their Examples and Uses	4
1.4 Different Levels of Materials Structure	5
1.4.1 Micro-Structure Levels	5
1.4.2 Dimensional Range and Examples	5
1.5 Requirements of Materials	6
1.5.1 Important Properties of Materials	6
1.5.2 Structure-Sensitive Properties	7
1.6 Structure-related Properties of Materials	7
1.6.1 Surface Related Properties	8
1.7 Factors to be Considered for Selection of Materials	8
1.7.1 Selection of Materials on the Basis of pH-Value of Liquid	9
1.8 Recent Advances in Materials Technology	10
1.9 Smart Materials (or Intelligent Materials)	11
1.9.1 Shape Memory Alloys	11
1.9.2 Advances in Smart Materials	12
1.9.3 Main Advantages of Smart (or Active) Materials	14
1.9.4 Other Examples of their Application	14

1.10	Nanotechnology	15
1.10.1	Processes to Prepare Nanomaterials	15
1.10.2	Uses of Nanotechnology	16
1.10.3	Future Prospects	17
1.10.4	Nano-Electro-Mechanical Systems (NEMs)	18
1.11	Functionally Graded Materials (FGMs)	18
1.11.1	Types of FGMs	19
1.11.2	Functional Properties	20
1.11.3	Processing of FGMs	20
1.11.4	Applications of FGMs	21
1.11.5	Future Prospects	21
1.12	Introduction to Biomedical Materials	22
1.12.1	Desired Functional Properties of Biomedical Materials	22
1.12.2	Some Key Applications of Biomaterials in Various Biodevices and Allied Components	23
	<i>Review Questions</i>	25
2.	ATOMIC MODELS AND BONDING IN SOLIDS	26—63
2.1	Atomic Models	26
2.2	Thomson's Atomic Model	26
2.3	Rutherford's Nuclear Atomic Model	26
2.3.1	Distance of Closest Approach	27
2.3.2	Scattring Angles	27
2.3.3	Assumptions in Rutherford Model	28
2.3.4	Major Deficiencies of Rutherford Atomic Model	29
2.4	Bohr's Quantum Atomic Model	29
2.4.1	Calculation of Radii of Orbits, Velocity and Frequency of Electrons	30
2.4.2	Normal, Excited and Ionized Atoms	31
2.4.3	Kinetic and Potential Energy of Electron	31
2.4.4	Energy Level for Hydrogn Atom	32
2.4.5	Deficiencies of Bohr's Atomic Model	32
2.5	Sommerfeld's Relativistic Atomic Model	33
2.6	Modern Concept of Atomic Model	34
2.6.1	de Broglie Wave	35
2.6.2	Wavelength of Electron Wave	35
2.6.3	Concept of Standing Wave	35
2.7	Quantum States	36
2.8	Electron Configuration	37
2.9	Meaning of Chemical (or Atomic) Bonding	37
2.9.1	Coulomb's Force in Bonding	37
2.10	Classification of Chemical Bonds	38
2.10.1	Directional and Non-Directional Bonds	39

2.11	Bonding Forces	39
2.11.1	Variation in Bonding Forces as a Function of Atomic Distance	39
2.12	Bond Length.....	40
2.12.1	Factors Affecting the Bond Length	40
2.12.2	Atomic Bonding vs Ionic Bonding	41
2.13	Theoretical Strength	41
2.14	Bond Energy	42
2.14.1	Minimum Potential Energy and Maximum Stability of Materials	42
2.14.2	Summary of Results	43
2.15	Ionic Bond	44
2.15.1	Mechanism of Bond Formation in NaCl	45
2.15.2	Reason of Formation of Non-Directional Bond in Ionic Solid	45
2.15.3	Requirements of Bond Formation in Ionic Solid	46
2.16	Covalent Bond	47
2.16.1	Concept of Covalent Bond Formation	47
2.16.2	Types of Covalent Bonds	48
2.16.3	Hybrid Bonds	49
2.16.4	Bond Angle	49
2.17	Metallic Bond	50
2.17.1	Mechanism of Metallic Bond Formation	50
2.18	Hydrogen Bond	51
2.18.1	Value of Dipole Moment	51
2.19	Van der Waals Bond	52
2.19.1	Mechanism of Bond Formation	52
2.20	Mixed Bond	52
2.21	Comparison of Bonds	53
2.22	Effects of Bonding Character on Properties of Materials	53
2.22.1	Correlation between the Properties	54
2.23	Ionization Energy	55
2.23.1	Factors Affecting Ionization Energy	56
2.24	Electron Affinity	57
2.25	Electronegativity	58
2.25.1	Effect of Electronegativity on the Character of Ionic and Covalent Bonds	58
2.25.2	Effect of Electronegativity on Bond Formation	59
2.25.3	Determining the Percentage Ionic Character of Compound Semiconductors	60
	<i>Review Questions</i>	60
	<i>Numerical Problems</i>	62
3.	CRYSTAL GEOMETRY OF METALS AND MILLER INDICES	64—104
3.1	Monocrystalline and Polycrystalline Crystal Structures	64
3.2	Space Lattice	65
3.3	Basis	66

3.4	Unit Cell and Crystal	67
3.5	Bravais Crystal System	68
3.6	Crystal Symmetry	71
3.6.1	Different Kinds of Symmetry	71
3.7	Primitive and Non-primitive Unit Cells	73
3.8	Coordination Number	73
3.9	Relation between Atomic Radius and Lattice Constant of SC, FCC and BCC	74
3.9.1	Simple Cube (SC)	74
3.9.2	Face Centred Cube (FCC)	74
3.9.3	Body Centred Cube (BCC)	75
3.10	Effective Number of Atoms	75
3.11	Atomic Packing Fraction	76
3.11.1	Atomic Packing Factor in SC Structure	77
3.11.2	Atomic Packing Factor in BCC Structure	77
3.11.3	Atomic Packing Factor in FCC Structure	77
3.12	Calculation of Density (or Bulk Density)	79
3.13	Miller Indices: The Crystallographic Notation of Atomic Planes	81
3.13.1	General Procedure to Find Miller Indices	82
3.13.2	Determining Miller Indices of a Given Plane	82
3.13.3	Drawing a Plane Whose Miller Indices are Given	83
3.13.4	Drawing a Plane which is Parallel to an Axis	83
3.13.5	Planes with Negative Indices	83
3.13.6	Family of Planes	84
3.13.7	Miller Indices: Crystallographic Notation of Atomic Crystal Directions	86
3.13.8	Alternate Method of Drawing a Direction	87
3.13.9	Direction with Negative Indices	87
3.13.10	Family of Directions	87
3.14	Miller-Bravais Indices	88
3.14.1	Depiction of Different Miller-Bravais Indices	88
3.15	Salient Features of Miller Indices	90
3.15.1	Some Common Planes and Directions	90
3.16	Interplaner Spacing	91
3.16.1	Relation among Interplaner Spacing, Lattice Constant and Miller Indices	92
3.16.2	Spacings between Important Sets of Planes	93
3.17	Linear Density	95
3.18	Planer Density	97
3.18.1	Planer Density in Simple Cube (SC) on (100) Plane	97
3.18.2	Planer Density in SC on (110) Plane	97
3.18.3	Planer Density in SC on (111) Plane	98
3.18.4	Planer Density in Body Centred Cube (BCC) on (100) Plane	98
3.18.5	Planer Density in BCC on (110) Plane	99
3.18.6	Planer Density in BCC on (111) Planer	99
3.18.7	Planer Density in Face Centred Cube (FCC) on (100) Plane	100

3.18.8	Planer Density in FCC on (110) Plane	100
3.18.9	Planer Density in FCC on (111) Plane	100
	<i>Review Questions</i>	102
	<i>Numerical Problems</i>	103
4.	SOLID STRUCTURES AND ALLOTROPY	105—133
4.1	Crystallography	105
4.2	Crystalline and Non-crystalline Structures	105
4.2.1	Factors Promoting Non-Crystallinity	106
4.3	Classification of Solids	107
4.4	Metallic Solids	107
4.4.1	Packing Style of Atoms in HCP	107
4.4.2	Packing Pattern of Atoms in FCC	108
4.4.3	Difference in Packing Patterns of HCP and FCC	109
4.5	Polymorphism (or Allotropy)	109
4.6	Hexagonally Closed Packed Structure (HCP)	111
4.6.1	Effective Number of Lattice Points in HCP	112
4.6.2	Effective Number of Atoms in HCP Structure	112
4.6.3	Coordination Number in HCP Structure	112
4.6.4	<i>c/a</i> Ratio for Ideally Closed Packed HCP Crystal	113
4.6.5	Atomic Packing Fraction (APF) in HCP	114
4.6.6	Planer Atomic Density on HCP	116
4.7	Voids	116
4.7.1	Tetrahedral Voids	116
4.7.2	Derivation for the Maximum Size of a Foreign Atom that can Fit into a Tetrahedral Void	117
4.7.3	Octahedral Void	118
4.7.4	Derivation of the Maximum Size of Foreign Atom that can Fit into Octahedral Void	118
4.8	Ionic Solids	119
4.8.1	Ligancy	119
4.8.2	Cation-Anion Configuration	120
4.9	Structures of Sodium Chloride, Cesium Chloride and Other Ionic Solids	123
4.9.1	Structure of NaCl	123
4.9.2	Structure of CsCl	123
4.9.3	Structure of Other Ionic Solids	124
4.10	Covalent Solids	126
4.10.1	Diamond Cubic (DC) Structure	127
4.10.2	Number of Atoms per Lattice Point and Basis in DC Structure	128
4.10.3	Distance of Separation between Two Atoms in DC	128
4.10.4	Atomic Packing Efficiency for DC	129
4.10.5	Density of Diamond	129
4.10.6	Graphite Structure	130
4.11	Complex Crystal Structures	131
	<i>Review Questions</i>	131
	<i>Numerical Problems</i>	132

5. MATERIALS CHARACTERIZATION (X-RAY DIFFRACTION AND MICROSCOPIC METHODS)	134—164
5.1 Structure Determining Techniques	134
5.2 X-rays	134
5.2.1 Production of X-rays	134
5.2.2 Laue X-rays Diffraction	135
5.3 Bragg's Law of X-rays Diffraction	135
5.3.1 Bragg's Equation	135
5.3.2 Reflections from Various Sets	136
5.4 Structure Determination	137
5.4.1 Consideration of First-order Reflection	137
5.4.2 Determining the Type of Cubic Lattice	138
5.4.3 Systematic Absences	138
5.4.4 Phase Difference between Two Atoms in a Single Unit Cell	139
5.4.5 Diagrammatic Representation of Extinction Rule	139
5.4.6 Extinction Rule	139
5.5 Powder Crystal Method (i.e. Debye-Scherrer Method)	142
5.5.1 Experimentation of Powder Crystal Method	142
5.5.2 Determining the Particle Size of Very Small Crystals	144
5.6 Microscopy	147
5.6.1 Microscopic Principle	147
5.6.2 Ray Diagram and Principle of Magnification	148
5.6.3 Magnifying Power of Microscope	149
5.7 Different Types of Metallurgical Microscopes and their Features	149
5.7.1 General Purpose Binocular Microscope	150
5.7.2 Inverted Metallurgical Microscope	151
5.8 Microscopic Methods	152
5.8.1 Advanced Methods	152
5.9 Preparation of Test Specimen/Sample	152
5.9.1 Fine Grinding	154
5.9.2 Rough Polishing	154
5.9.3 Fine Polishing	154
5.9.4 Etching	154
5.10 Working Principle of Electron Microscope	155
5.10.1 Formation of Magnified Image	155
5.11 Microstructural Examination	156
5.12 ASTM Number	157
5.12.1 Methods of Grain Size Measurement	157
5.12.2 Determination of Grain Size	157
5.12.3 Coarse to Ultrafine Range of Grains	158
5.13 Comparative Study of Microstructures of Various Metals and Alloys such as Mild Steel, Cast Iron, Brass etc.	159
5.13.1 Microstructure of Mild Steel	159

5.13.2	Microstructure of Cast Iron	160
5.13.3	Microstructure of Brass	160
5.13.4	Microstructure of Bronze	160
5.13.5	Microstructure of Nodular (Spheroidal) Cast Iron	160
5.13.6	Microstructure of High Speed Steel (HSS)	160
5.13.7	Microstructure of Other Steels	162
	<i>Review Questions</i>	163
	<i>Numerical Problems</i>	164
6.	CRYSTAL IMPERFECTIONS	165—195
6.1	Ideal and Real Crystals, and Imperfections	165
6.1.1	Disadvantageous Effects of Imperfections	165
6.1.2	Advantageous Effect of Imperfection	165
6.2	Classification of Imperfections	166
6.3	Point Imperfections	166
6.3.1	Vacancy	166
6.3.2	Substitutional Impurity	167
6.3.3	Interstitial Impurity	167
6.3.4	Frenkel's Defect	168
6.3.5	Calculation for Number of Frenkel's Defect in Ionic Solids	168
6.3.6	Schottky's Defect	170
6.4	Effects of Point Imperfections	170
6.4.1	Origin of Point Imperfections	170
6.4.2	Enthalpy of Formation of Point Imperfections	171
6.5	Line Imperfections	172
6.6	Features of Edge Dislocation	172
6.6.1	Stress Field in Edge Dislocation	172
6.6.2	Reason of Induction of Extra Strain Energy	172
6.6.3	Positive and Negative Type Edge Dislocations	173
6.6.4	Slip or Glide Plane	173
6.7	Burgers Circuit and Burgers Vector in Edge Dislocation	173
6.7.1	Burgers Circuit in a Perfect Crystal	173
6.7.2	Burgers Circuit in an Imperfect Crystal	174
6.8	Screw Dislocation	175
6.8.1	Stress-Strain Field in Screw Dislocation	175
6.8.2	Burgers Circuit in Screw Dislocation	175
6.9	Mixed Dislocation	176
6.9.1	Burgers Circuit for Mixed Dislocation	176
6.10	Characteristics of Dislocations	177
6.10.1	Burgers Vectors of Dislocations in Cubic Crystals	178
6.11	Force Required to Move a Dislocation	179
6.11.1	Peierls and Nabarro Stress	179
6.12	Energy of Dislocation	179

6.13	Sources of Dislocations, Their Effects and Remedies	180
6.13.1	Effects of Dislocations	181
6.13.2	Remedies to Minimise the Dislocations	181
6.14	Phenomena Related to Behaviour of Dislocations	181
6.14.1	Glide Motion of Dislocation	182
6.14.2	Reason as to Why a Screw Dislocation Cannot Have a Glide Motion	182
6.15	Dislocation Climb	183
6.15.1	Mechanism of Climb-up and Climb-down Motion	183
6.16	Cross-Slip	184
6.17	Jogs in Dislocation	185
6.18	Interaction of Dislocations with Point Imperfections	185
6.19	Surface Imperfections	186
6.20	Grain Boundary	186
6.21	Twin or Twinning	187
6.21.1	Annealing Twin and Deformation Twin	187
6.22	Low Angle Tilt Boundary	188
6.23	Other Crystal Boundaries	189
6.23.1	Stacking Fault	189
6.24	Volume Imperfections	189
6.25	Whiskers	190
6.25.1	Difference between Bulk, Fibre and Whisker Forms of Material	190
6.25.2	Effects of Size of Whiskers on Mechanical Properties of Materials	190
6.25.3	Effects of Temperature on Properties of Whiskers	191
6.26	Solved Examples	192
	<i>Review Questions</i>	193
	<i>Numerical Problems</i>	194
7.	DIFFUSION IN SOLIDS	196—220
7.1	Introduction: Diffusion and its Causes	196
7.2	Diffusion Controlled Applications	196
7.3	Types of Diffusion	197
7.3.1	Sub-Classification of Microscopic Diffusion	197
7.4	Mechanism of Atomic Diffusion	197
7.4.1	Vacancy Mechanism	198
7.4.2	Interstitial Mechanism, Potential Energy Barrier and Enthalpy of Motion	198
7.4.3	Substitutional Mechanism	199
7.4.4	Direct Interchange Mechanism	199
7.5	Diffusion Processes	199
7.5.1	Process of Self Diffusion and its Mechanism	200
7.5.2	Inter-Diffusion	201
7.5.3	Lattice Diffusion	201
7.5.4	Pipe Diffusion	202
7.6	Laws of Diffusion	202

7.7	Fick's First Law of Diffusion	202
7.7.1	Diffusivity and Factors Affecting the Diffusivity	203
7.8	Fick's Second Law of Diffusion	204
7.8.1	Derivation of Non-Steady State Flow	204
7.9	Limitation of Fick's Laws	205
7.10	Solution to Fick's Second Law	205
7.10.1	Solution by Error Function Method	206
7.11	Experimental Determination of Diffusivity	207
7.11.1	Experimental Procedure to Determine Diffusivity	208
7.11.2	Diffusivity as a Function of Temperature	208
7.12	Applications Based on Second Law	208
7.12.1	Case Hardening (or Carburizing) of Steel	208
7.12.2	Mechanism of Diffusion and Derivation during Carburising	209
7.12.3	Decarburization of Steel	210
7.12.4	Mechanism of Diffusion and Derivation during Decarburization	210
7.12.5	Imparting Corrosion Resistance to Duralumin	212
7.12.6	Doping of Semiconductor by Diffusion	214
7.13	Factors Affecting Diffusivity	217
7.14	Kirkendall Effect	218
	<i>Review Problems</i>	219
	<i>Numerical Problems</i>	219
8.	PHASES AND PHASE DIAGRAMS	221—255
8.1	Introduction : Overview	221
8.2	Terminologies Defined	221
8.3	Solid Phases in Alloys	222
8.3.1	Forms of Solid Phases	223
8.4	Solid Solution	223
8.4.1	Interstitial Solid Solution	223
8.4.2	Substitutional Solid Solution	224
8.4.3	Hume-Rothery's Rule	224
8.5	Intermetallic Compounds and Intermediate Compounds	225
8.5.1	Valency Intermetallic Compounds	225
8.5.2	Electron Intermetallic Compounds	225
8.5.3	Definite Radii Ratio Intermetallic Compound	225
8.5.4	Intermediate Compounds (or Phases)	225
8.5.5	α , β , γ Phase of Brass i.e. α -brass, β -brass, γ -brass etc.	226
8.6	Phases	226
8.6.1	Single-phase and Multi-phase Solids	227
8.7	Gibb's Phase Rule	227
8.7.1	Total Number of Variables in a System	227
8.7.2	Limitation of Degree of Freedom	227
8.8	Phase Diagrams	228

8.9	Unary Phase Diagrams	228
8.9.1	Unary Phase Diagram of Iron	228
8.9.2	Unary Phase Diagram of Carbon	229
8.10	Binary Phase Diagram	230
8.10.1	Solidus and Liquidus, and Tie Line	231
8.10.2	Variables for Two-phase Region	232
8.10.3	Binary Isomorphous Phase Diagram	232
8.10.4	Invariant Reactions	232
8.11	Different Types of Binary Phase Diagrams	233
8.12	Eutectic Phase Diagram	233
8.12.1	Phase Diagram of Lead-Tin System	234
8.13	Eutectoid Phase Diagram	236
8.13.1	Hypo-eutectoid and Hyper-eutectoid	236
8.14	Peritectic Phase Diagram	237
8.15	Peritectoid Phase Diagram	238
8.16	Microstructural Changes	239
8.16.1	Effect of Cooling on Microstructure Formation	240
8.16.2	Coring and Dendritic Structure	240
8.17	Lever Rule	241
8.17.1	Proof of Lever Rule	241
8.17.2	Applicability and Non-Applicability Conditions of Lever Rule	244
8.18	Interpretation of Phase Diagrams	244
8.18.1	Determination of the Phases Present	244
8.18.2	Determination of Phase Composition	245
8.18.3	Isotherm	245
8.18.4	Determination of Phase Amount	245
8.19	Typical Phase Diagrams	248
8.20	Iron-Carbon System	248
8.20.1	Eutectoid Point	248
8.20.2	Eutectic Point	248
8.20.3	Effect of Percentage of Carbon on Melting Point	249
8.20.4	Hypoeutectoid Alloys	250
8.21	Alumina-Silica System	251
8.22	Copper-Beryllium System	251
8.23	Applications of Phase Diagrams	252
8.24	Ternary Phase Diagram	252
8.24.1	Pseudo Ternary Diagram	253
8.24.2	Designation of a Ternary Phase on a 2-Dimensional Diagram	253
	<i>Review Questions</i>	254
	<i>Numerical Problems</i>	255

9. MECHANICAL PROPERTIES	256—293
9.1 Importance of Mechanical Properties	256
9.1.1 Some Extreme Situations Under Which the Materials Work	256
9.2 Basic Properties	257
9.2.1 Elongation, Strain and Stress at Atomic Level	257
9.2.2 Young's Modulus	258
9.2.3 Factors Affecting the Young's Modulus	259
9.3 Elastic Constants	260
9.3.1 Poisson's Ratio	260
9.3.2 Shear Modulus (or Modulus of Rigidity)	260
9.3.3 Bulk Modulus	261
9.3.4 Relation Among Different Elastic Constants	261
9.4 Isotropic, Anisotropic and Orthotropic Materials	262
9.4.1 Isotropy, Orthotropy, and Anisotropy	262
9.4.2 Homogeneity and Heterogeneity	263
9.5 Stress-strain Diagrams	266
9.5.1 Tensile Stress-Strain Diagrams	266
9.5.2 Compressive Stress-Strain Diagrams	268
9.5.3 Shear Stress-Shear Strain (η vs γ) Diagrams	269
9.6 Stress-strain Diagram of Structural Steel	269
9.6.1 Proportional Limit, Elastic Limit and Yield Point	270
9.6.2 Factors Affecting Stress-Strain Diagrams	271
9.6.3 Prediction of Properties on the Basis of Nature of Elastic Curve	271
9.7 Elastic Properties	272
9.8 Linear Elastic Properties	272
9.8.1 Strain Energy Absorbed by the Materials	272
9.8.2 Bi-Modulus Material	273
9.9 Nonlinear Elastic Properties	273
9.9.1 Secant Modulus	273
9.9.2 Tangent Modulus	273
9.9.3 Damping Property and Mechanical Hysteresis Loop	275
9.9.4 Offset Methods to Determine Proof Stress	275
9.10 Other Mechanical Properties	276
9.10.1 Strength	276
9.10.2 Stiffness	277
9.10.3 Resilience, Proof Resilience and Toughness	277
9.10.4 Elasticity and Plasticity	277
9.10.5 Ductility and Brittleness	278
9.10.6 Malleability	279
9.10.7 Hardness	279
9.11 Fatigue	279
9.11.1 Main Effects of Fatigue	279
9.11.2 Fatigue Limit (or Endurance Stress) and S-N Diagram	281

9.11.3	Critical Applications of Fatigue Behaviour	281
9.11.4	Mechanism of Fatigue Fracture	282
9.11.5	Types of Fatigue Fracture	282
9.11.6	Improving the Fatigue Life	283
9.12	Creep	283
9.12.1	Critical Applications for Creep Consideration	283
9.12.2	Creep Curves	283
9.12.3	Creep Fracture	284
9.12.4	Different Stages of Creep Curves	285
9.12.5	Creep Laws	285
9.12.6	Factors Affecting Creep	287
9.12.7	Mechanism of Creep	288
9.12.8	Creep Resistant Materials	289
9.12.9	Advanced Creep Resisting Materials	289
	<i>Review Questions</i>	290
	<i>Numerical Problems</i>	292
10.	MECHANICAL TESTS, AND FACTORS AFFECTING THE MECHANICAL PROPERTIES	294—337
10.1	Destructive and Non-Destructive Testings	294
10.1.1	Different Techniques of Non-Destructive Tests	294
10.2	Destructive Tests	294
10.3	Tensile Test	295
10.3.1	Universal Testing Machine	295
10.3.2	Tensile Testing Specimen and Gauge Length	295
10.3.3	Procedure of Tensile Testing	297
10.3.4	Observations and Calculation	297
10.4	Compression Test	301
10.4.1	Test Set-up, Specifications of Machines, and Specimen Details	301
10.4.2	Limitations of the Test	302
10.4.3	Failure Mode of Compression Specimen	302
10.4.4	Observations, Calculations and Results	303
10.5	Shear and Bending (or Flexure) Tests	305
10.5.1	Three-point and Four-point Beam Bending Test	305
10.5.2	Calculation for the Result	306
10.5.3	Plot of the Likely Stress-Strain Diagram in Pure Bending	306
10.6	Torsion Test	308
10.6.1	Torque vs Twist Diagram	308
10.6.2	Calculation to Determine Torsional Shear Stress	308
10.6.3	Plot of the Curve between Shear Stress and Shear Strain under Torsion	309
10.7	Hardness Tests	309
10.7.1	Mohs Test	310

10.8	Brinell Hardness Test	311
10.8.1	Test Set-up, Specifications of Hardness Testing Machines, and Indentors	311
10.8.2	Test Procedure	311
10.8.3	Observations and Calculations	312
10.8.4	Test Requirements and Limitations	312
10.9	Rockwell Hardness Test	314
10.9.1	Indenter and Test Procedure	314
10.9.2	Suitable Applications	315
10.10	Vickers Hardness Test	315
10.11	Knoop Hardness Test	316
10.11.1	Microhardness Test	317
10.12	Shore Hardness Test	317
10.12.1	Durometer	317
10.13	Barcol Hardness Test	317
10.14	Jominy's End-Quenched Test	317
10.15	Rebound Hardness Test	318
10.16	Impact Tests	318
10.16.1	Machine Set-up and Test Procedure	318
10.16.2	Types of Impact Tests and Specimens	318
10.16.3	Purpose of Keeping a Notch	320
10.16.4	Meaning of Notch Effect and Notch Sensitivity	320
10.16.5	Result	320
10.17	Fatigue Test	322
10.17.1	Experimental of Test Set-up	322
10.17.2	Statistical Nature of Fatigue Test	323
10.17.3	Determination of Endurance Stress	323
10.18	Creep Test	324
10.18.1	Expected Life of Machines and Equipment	325
10.18.2	Experimental Set-up of Creep Testing Machine	325
10.18.3	Result of the Experiment	326
10.19	Factors Affecting Mechanical Properties	326
10.20	Effect of Grain Size	326
10.20.1	Hall-Petch Consideration	327
10.20.2	Determining the ASTM Number	327
10.20.3	Grain Size Calculation	328
10.20.4	Coarse to Ultrafine Range of Grains	328
10.20.5	Effects of Fine and Coarse Grained Materials on Properties of Materials	329
10.21	Effect of Radiation	331
10.21.1	Effects of Nuclear Radiation	331
10.22	Solved Examples	332
	<i>Review Questions</i>	333
	<i>Numerical Problems</i>	335

11. THEORIES OF INELASTIC, ANELASTIC AND VISCOELASTIC DEFORMATIONS, AND FRACTURE	338—379
11.1 Different Types of Deformations	338
11.2 Elastomeric Deformation	339
11.3 Plastic (or Inelastic) Deformation	339
11.3.1 Phenomenon of Deformation by Slip	340
11.4 Various Slip Systems	340
11.4.1 Slip System in Face Centred Cube (FCC)	341
11.4.2 Slip System in Body Centred Cube (BCC)	341
11.4.3 Slip System in Hexagonally Closed Packed (HCP)	342
11.5 Phenomenon of Deformation by Dislocation and Twinning	342
11.6 Critical Resolved Shear Stress (CRSS)	342
11.6.1 Derivation for the Stress at which the Slip Starts	342
11.6.2 Maximum Value of Tangential Shear Stress to Start the Slip	343
11.7 Yielding	344
11.7.1 Types of Yielding	344
11.7.2 Mechanism of Continuous Yielding	345
11.7.3 Mechanism of Discontinuous Yielding	345
11.7.4 Special Yielding Effects	346
11.8 Strain Hardening (or Work Hardening)	347
11.8.1 Mechanism of Strain Hardening	348
11.8.2 Effects of Strain-Hardening	349
11.9 Frank-read Source: An Effect of Plastic Deformation	350
11.9.1 Mechanism of Frank-Read Source	350
11.9.2 Operating Limitation of Frank-Read Source	351
11.9.3 Dislocation Velocity and Straining Rate	352
11.10 True Stress-strain (ζ - ϵ) Diagrams	352
11.10.1 True ζ - ϵ Diagram Under Tensile Loading	353
11.10.2 True ζ - ϵ Diagram Under Compressive Load	354
11.10.3 Relation between True and Conventional Strains	355
11.10.4 True Stress-True Strain Curve and Superplastic Behaviour of Materials	356
11.10.5 Superplastic Materials	356
11.11 Repeated Loading and Unloading in Plastic Range	358
11.11.1 Repeated Loading and Unloading in Plastic Range under Tension	358
11.11.2 Repeated Loading and Unloading in Plastic Range under Compression	358
11.12 Bauschinger Effect (i.e. Repeated Loading and Unloading Alternately in Tension and Compression)	358
11.12.1 Mechanism of Bauschinger Effect	360
11.13 Anelastic Behaviour	360
11.13.1 Elastic Aftereffect (or Delayed Elasticity)	360
11.13.2 Effect of Rate of Loading	361
11.13.3 Relaxation Processes and Relaxation Time	362
11.13.4 Effect of Temperature on Relaxation Time	362

11.14	Viscoelastic Behaviour	363
11.14.1	Maxwell's Series Model	363
11.14.2	Voigt-Kelvin Model	364
11.15	Meaning of Fracture and its Types	365
11.16	Ductile Fracture	365
11.16.1	Types of Fractured Ends in Ductile Failure	366
11.17	Brittle Fracture	367
11.18	Griffith's Theory of Crack Propagation	367
11.18.1	Condition of Propagation of Crack	368
11.18.2	Importance of Stress Concentration at the Crack Tip	369
11.18.3	Salient Features of Griffith Theory	369
11.18.4	Griffith-Orowan Criterion	371
11.19	Cleavage Fracture	372
11.19.1	Characteristics of Cleavage	372
11.19.2	Types of Cleavage Fracture	373
11.20	Methods of Protection Against Fracture	373
11.21	Ductile-brittle Transition	373
11.21.1	Conditions Responsible for Brittle Fracture of Ductile Metals	374
11.21.2	Factors Affecting the Transition Temperature	375
11.21.3	Effects of Ductile-Brittle Transition	375
11.22	Fractography	375
11.23	Solved Examples	376
	<i>Review Questions</i>	376
	<i>Numerical Problems</i>	378
12.	ORGANIC MATERIALS: PLASTICS RUBBER, ELASTOMER AND WOOD	380—406
12.1	Introduction to Organic Materials	380
12.2	Meaning of Monomers and Polymers	380
12.3	Degree of Polymerization	381
12.4	Mechanism of Polymerization	382
12.4.1	Addition Polymerization	383
12.4.2	Copolymerization	383
12.4.3	Condensation Polymerization	384
12.5	Additives in Polymers	385
12.6	Strengthening Mechanisms of Polymers	386
12.6.1	Crystallization	386
12.6.2	Cross-Linking	387
12.6.3	Chain-Stiffening	387
12.7	Deformation of Polymers	388
12.8	Various Types of PLASTICS and their Applications	388
12.8.1	Thermosetting Plastics	389
12.8.2	Thermoplastics	389
12.8.3	Comparison between Thermosets and Thermoplasts	390

12.9	Polymeric Fibres	391
12.9.1	Properties of Various Synthetic and Natural Fibres	391
12.10	Mechanical Behaviour of Plastics	392
12.11	Processing of Plastics	393
12.12	Rubber	393
12.12.1	Different Types of Processed Natural Rubber	394
12.12.2	Synthetic Rubber	394
12.13	Elastomer	395
12.13.1	Method of Producing Elastomer from Raw Rubber	395
12.13.2	Vulcanizing Agents	395
12.14	Behaviour of Polymers under Different Situations	397
12.14.1	Thermal Behaviour of Polymers	398
12.14.2	Glass-Transition Temperature	399
12.15	Future of Plastics	399
12.15.1	Expanding Plastics	400
12.15.2	Conducting Polymers	400
12.15.3	Polymers in Electronics	400
12.15.4	Thermoplast-Thermoset Plastics	400
12.15.5	Liquid Crystal Polymers (LCP)	401
12.15.6	Photocurable Polymers	401
12.15.7	Biomedical Polymers	401
12.15.8	Polymer Foams	402
12.16	Photorefractive Polymers	402
12.17	Wood	403
12.18	Solved Examples	404
	<i>Review Questions</i>	405
	<i>Numerical Problems</i>	406
13.	AMORPHOUS MATERIALS: CERAMICS, REFRACTORIES AND GLASSES ETC. . 407—421	
13.1	Ceramic Materials	407
13.1.1	Basic Ceramic Structure	407
13.2	Types of Ceramics	407
13.3	Refractories	409
13.3.1	Refractoriness	409
13.3.2	Types of Refractories	410
13.3.3	Properties of Refractories	410
13.4	Silica and Silicates	410
13.4.1	Crystalline and Non-crystalline Forms of Silica	410
13.4.2	Configuration of Minerals	410
13.5	Applications of Ceramics	411
13.6	Mechanical Behaviour of Ceramics	412
13.6.1	Other Behaviour of Ceramics	413
13.7	Electrical Behaviour of Ceramics	413

13.8	Processing of Ceramics	413
13.8.1	Glass Forming Processes	414
13.9	Glasses	414
13.9.1	Glass-Forming Constituents	415
13.9.2	Divitrified Glass	415
13.10	Types of Glasses	415
13.10.1	Soda Lime Glasses	416
13.10.2	Lead Glasses	416
13.10.3	Borosilicate Glasses	416
13.10.4	High Silica Glasses	416
13.10.5	Photochromatic and Zena Glasses	416
13.11	Perovskite Structures (or Mixed Oxides)	417
13.12	Reinforced Cement Concrete (RCC)	417
13.12.1	Ingredients of RCC	417
13.12.2	Grades and Strength of RCC	418
13.12.3	Reinforcing Materials	418
13.12.4	Advantages of RCC	418
13.13	Clays and Clay-based Ceramics	419
13.14	Chemically Bonded Ceramics	419
13.15	Solved Examples	420
	<i>Review Questions</i>	420
14.	COMPOSITE MATERIALS	422—454
14.1	Introduction	422
14.2	Laminated Composites	422
14.3	Reinforced Composite Materials	423
14.3.1	Classification of Reinforced Composite Materials	423
14.4	Particulate Composites	425
14.4.1	Dispersion-Strengthened Composites	425
14.4.2	Cermets	425
14.4.3	Rubber Toughened Polymers	426
14.5	Flake Composites	426
14.6	Whisker Reinforced Composites	426
14.7	Hybrid Composites	426
14.7.1	Types of Hybrid Composites	427
14.8	Sandwich Composites	427
14.8.1	Honeycomb Materials	427
14.8.2	Flexural Rigidity of Sandwich Beam	428
14.8.3	Historical Application	429
14.9	Advantages and Limitations of Composites	430
14.9.1	Advantages	430
14.9.2	Limitations	430
14.9.3	Comparison between Conventional and Composite Materials	431

14.10	Various Types of Fibres and Their Aspect Ratio	431
14.10.1	Aspect Ratio of Fibres	432
14.10.2	Glass Fibres	432
14.10.3	Boron Fibre	433
14.10.4	Carbon and Graphite Fibres	433
14.10.5	Kevlar Fibre	433
14.10.6	Ceramic Fibres	434
14.10.7	High Performance Fibres	434
14.10.8	Natural Fibres	435
14.11	Configurations of Reinforcing Fibres	436
14.11.1	Forms of Fibres	436
14.11.2	Forms of End-Products	437
14.12	Various Matrix Materials	437
14.12.1	Mylar: A Form of Flake	437
14.12.2	MMC Composites	437
14.12.3	Wood-Plastic Composite	437
14.13	Mechanics of Composite Laminates	438
14.14	Rule of Mixture for Unidirectional Lamina	438
14.14.1	Volume Fraction and Weight Fraction	438
14.14.2	Density of Composite	438
14.14.3	Load on Composite	439
14.14.4	Longitudinal Strength and Modulus	439
14.14.5	Transverse Strength and Modulus	439
14.14.6	Poisson's Ratio	440
14.14.7	Shear Moduli	440
14.14.8	Range of Poisson's Ratio in Composite Materials	441
14.14.9	Modified Rule of Mixture for Non U/D Composites	443
14.15	Generalized Hooke's Law and Elastic Constants	445
14.15.1	Different Moduli and Coupling Coefficients	445
14.15.2	Major and Minor Poisson's Ratio	445
14.15.3	Number of Dependent and Independent Elastic Constants	445
14.16	Applications of Composite Materials	446
14.17	Stress-strain Behaviour of Fibres, Matrix and Composites	448
14.18	Basic Composite Manufacturing Methods	449
14.18.1	Prepreg Lay-up Process	449
14.18.2	Wet Lay-up (or Hand Lay-up) Process	450
14.18.3	Thermoplastic Pultrusion Process	450
14.18.4	Comparison of Various Manufacturing Processes	450
	<i>Review Questions</i>	452
	<i>Numerical Problems</i>	453

15. PHASE TRANSFORMATIONS AND MATERIAL STRENGTHENING MECHANISMS	455—479
15.1 Phase Transformations	455
15.2 Terminologies Related to Phase Transformation	456
15.3 Rate of Cooling and Crystallization	457
15.3.1 Temperature–Enthalpy Curves Depicting the Formation of Crystalline and Non-Crystalline Solids	457
15.3.2 Special Transformations	458
15.4 Solidification of Metals	458
15.4.1 Thermal Activation	459
15.5 Arrhenius Equation	459
15.5.1 Rate Law Processes	460
15.5.2 Arrhenius Plot	460
15.6 Meaning of Crystal Nucleation and Growth	462
15.6.1 Rate of Nucleation and the Rate of Nucleus Growth	462
15.7 Homogeneous Nucleation	462
15.7.1 Free Energy Barrier for Nucleation	463
15.8 Heterogeneous Nucleation	464
15.9 Crystal Growth Rate	464
15.9.1 Transformation Rate	465
15.9.2 Grain Size Control	465
15.10 Strengthening Mechanisms	466
15.11 Cold and Hot Working	467
15.11.1 Cold Working: Advantages and Disadvantages	467
15.11.2 Percentage of Cold Working	468
15.11.3 Effects of Cold Working	468
15.11.4 Hot Working: Advantages and Disadvantages	469
15.12 Precipitation (or Age) Hardening	469
15.12.1 Mechanism of Age Hardening	470
15.12.2 Age Hardening of Steel	471
15.13 Dispersion Strengthening	471
15.13.1 Factors Affecting Strengthening	471
15.13.2 Comparison between Dispersion Hardening and Precipitation Hardening	472
15.14 Solid Solution Hardening	472
15.15 Recovery and Recrystallization	473
15.15.1 Recovery (or Stress-Relieving Anneal)	474
15.16 Recrystallization	475
15.16.1 Recrystallization Temperature	476
15.16.2 Effect of Time and Temperature on Recrystallization	476
15.17 Grain Growth and Preferred Orientation	477
<i>Review Questions</i>	478
<i>Numerical Problems</i>	479

16. HEAT TREATMENT	480—504
16.1 Introduction to Heat Treatment	480
16.1.1 Classification of Various Heat Treatment Processes	480
16.2 Purpose of Heat Treatment	481
16.3 Microstructures of Steel and Iron	481
16.3.1 Allotropic Forms of Steel	482
16.4 Critical Points	483
16.5 Iron-carbon Phase (Equilibrium) Diagram	485
16.5.1 Hypoeutectoid and Hypereutectoid Steels	486
16.6 Transformation in Steel and Critical Cooling Curve	486
16.6.1 Effect of Rate of Cooling	486
16.6.2 Effect of Carbon Content on Hardness	488
16.7 Phase Transformation in Iron-Carbon Diagram	489
16.8 Heating Temperature Range in Various Heat Treatment Processes	490
16.9 Hardening	491
16.10 Quench Hardening	491
16.10.1 Effect of Quenching Rate	491
16.10.2 Effect of Quenching Media	492
16.11 Tempering	492
16.11.1 Purpose of Tempering	492
16.11.2 Low, Medium and High Temperature Tempering	493
16.11.3 Austempering	493
16.11.4 Martempering	493
16.12 Annealing	494
16.12.1 Objectives	494
16.12.2 Types of Annealing Processes	494
16.12.3 Process Annealing	494
16.12.4 Full Annealing	495
16.12.5 Spheroidise Annealing	495
16.12.6 Diffusion Annealing	495
16.13 Normalizing	496
16.13.1 Objectives of Normalizing	496
16.14 Case Hardening (or Carburizing)	497
16.14.1 Pack Carburizing	497
16.14.2 Liquid Carburizing	497
16.14.3 Gas Carburizing	497
16.15 Cyaniding	498
16.16 Nitriding	498
16.17 Carbo-nitriding Of Steel	498
16.18 Flame Hardening	499
16.19 Induction Hardening	499
16.20 Jominy End-quenched Test : A Method of Determining Hardenability	500
16.20.1 Variables Affecting the Hardenability of Steel and Alloy Steels	500

16.21	Overheated and Burnt Steel	501
16.21.1	Causes and Remedies of Overheating and Burning of Steel	502
16.22	Temper Brittleness : Its Causes and Remedies	502
16.23	Recent Advances	503
	<i>Review Questions</i>	503
17.	CORROSION AND OXIDATION	505—531
17.1	Introduction	505
17.2	Types of Corrosion	506
17.3	Wet Corrosion	506
17.3.1	Galvanic Cell	507
17.3.2	Illustration of Mg-Ni Galvanic Cell	507
17.3.3	Mechanism of Formation of Galvanic Cell	507
17.3.4	Examples of Corrosion due to Galvanic Cell	508
17.4	Types of Galvanic Cell Corrosions	508
17.4.1	Single Metal Corrosion	508
17.4.2	Concentration Corrosion	509
17.4.3	Crevice Corrosion	509
17.4.4	Water Line Corrosion	509
17.4.5	Stress Corrosion	509
17.5	Dry Corrosion	510
17.5.1	Types of Corrosion Film	511
17.5.2	Mechanism of Dry Corrosion	511
17.6	Laws of Corrosion	512
17.7	Oxidation	513
17.7.1	Rate of Oxidation	513
17.7.2	Methods to Reduce Oxidation	514
17.7.3	Mechanism of Oxidation	514
17.7.4	Pilling Bedworth Ratio	515
17.7.5	Protection Against Oxidation	515
17.8	Passivity	516
17.8.1	Improving the Passivity of Metals	516
17.9	Special Types of Corrosion	516
17.10	Stress Corrosion Cracking	516
17.10.1	Transcrystalline Corrosion	517
17.10.2	Intergranular Corrosion	517
17.10.3	Corrosion Environments that are Responsible for Stress Corrosion Cracking ...	517
17.11	Corrosion Fatigue	518
17.12	Fretting Corrosion	518
17.12.1	Method to Avoid Fretting Corrosion	518
17.13	Cavitation-Erosion Corrosion	519
17.13.1	Methods to Minimize the Cavitation-Erosion Corrosion	519
17.14	Caustic Embrittlement	519

17.15	Hydrogen Embrittlement	520
17.16	Dezincification	520
17.16.1	Silver Tarnishing	520
17.17	Season Cracking/Caustic Embrittlement	520
17.18	Pitting	521
17.19	Protection Against Corrosion and Oxidation	521
17.19.1	Use of Noble Metals	521
17.19.2	Use of Corrosion and Oxidation Resistant Materials	521
17.19.3	Use of Protective Coatings	523
17.19.4	Use of Inhibitors	523
17.19.5	Design to Avoid Formation of Galvanic Cell	524
17.19.6	Deaeration of Water	525
17.20	Cathodic Protection	525
17.20.1	Working Arrangement of Cathodic Protection	525
17.20.2	Protection of Petroleum Pipelines	526
17.21	Protective Coatings	527
17.22	Metallic Coatings	527
17.22.1	Electroplating	527
17.22.2	Dipping	527
17.22.3	Galvanising	527
17.22.4	Tinning	528
17.22.5	Spraying	528
17.22.6	Cladding	528
17.22.7	Cementation	528
17.22.8	Sheavdizing	528
17.22.9	Calorizing	528
17.22.10	Chromizing	528
17.23	Non-Metallic Coatings	528
17.23.1	Anodized Coatings	529
17.23.2	Surface Conversion (or Chemical Dip) Coating	529
17.24	Environmental Effect on Galvanic Series	529
	<i>Review Questions</i>	530
	<i>Numerical Problems</i>	531
18.	ELECTRON THEORIES, AND CONDUCTING MATERIALS: PROPERTIES, BEHAVIOUR AND APPLICATIONS	532—555
18.1	Electrons and Their Role in Conductivity	532
18.1.1	Valence and Free Electrons	532
18.2	Electron Theories of Solids	532
18.3	Free Electron Theory	533
18.3.1	Kinetic Energy in Terms of Wave Number	533
18.3.2	Kinetic Energy in Terms of Length of the Solid	534
18.3.3	Energy Equation for 3-Dimensional Solid	535

18.3.4	Mechanism of Conduction by Free Electrons	535
18.3.5	Drift Velocity and Collision Time	536
18.3.6	Mean Free Path (or Mean Free Length)	538
18.3.7	Effect of Temperature on Mean Free Path	538
18.4	Energy Band Theory	539
18.4.1	Magnitude of Energy Gap	540
18.5	Brillouin Zone Theory	540
18.5.1	Different Brillouin Zones	541
18.5.2	First and Second Brillouin Zones	542
18.5.3	Brillouin Zones for Simple Cubic Lattice	542
18.5.4	Brillouin Zones for BCC, FCC and HCP Lattices	543
18.6	Classification of Solids on the basis of Energy Gap	544
18.6.1	Energy Gap for Different Solids	545
18.6.2	Comparison Among Conductors, Semiconductors and Insulators	546
18.7	Conductors	546
18.7.1	Characteristics of a Good Conductor	547
18.8	Factors Affecting Conductivity (and Resistivity) of Metals	547
18.8.1	Temperature Effect on Conductivity	548
18.8.2	Nordheim Equation for Impurity and Alloying Effects	549
18.8.3	Effect of Plastic Deformation	549
18.8.4	Matthilseen Rule of Total Resistivity	549
18.9	Types of Conducting Materials	550
18.10	Copper	551
18.10.1	Types of Copper	551
18.11	Aluminium	552
18.11.1	Types of Aluminium	552
18.11.2	Comparison of Different Conducting Metals with Steel	553
	<i>Review Questions</i>	553
	<i>Numerical Problems</i>	554
19.	SEMICONDUCTING MATERIALS: PROPERTIES, BEHAVIOUR	
	AND APPLICATIONS	556—588
19.1	Introduction to Semiconductors	556
19.1.1	Properties of Semiconductors	556
19.2	Different Types of Semiconducting Materials	557
19.2.1	Silicon	557
19.2.2	Germanium	558
19.2.3	Selenium (Se)	558
19.2.4	Merits of Semiconducting Materials	559
19.2.5	Characteristics of Semiconducting Materials	559
19.3	Fermi Energy Level	559
19.3.1	Fermi-Dirac Probability Function and Temperature Effect	560

19.4	Intrinsic Semiconductors	561
19.4.1	Energy Diagram of Intrinsic Semiconductor	562
19.4.2	Holes, Mobility and Conductivity	562
19.5	Extrinsic Semiconductors	563
19.5.1	<i>n</i> -Type Semiconductors and their Energy Diagram	564
19.5.2	Law of Mass Action	564
19.5.3	<i>p</i> -Type Semiconductors and their Energy Diagram	565
19.6	Effective Mass	567
19.7	Density of State	568
19.8	Formulated (Compound and Alloyed) Semiconducting Materials	570
19.8.1	Gallium Arsenide (GaAs)	570
19.8.2	Indium Antimonide (InSb)	570
19.8.3	Oxides, Sulphides, Halides, Tellurides and Selenides	571
19.8.4	Cadmium Sulphide (CdS)	571
19.8.5	Silicon Carbide (SiC)	571
19.8.6	Lead Sulphide (PbS)	572
19.9	Basic Semiconducting Devices and Their Operating Principle	572
19.9.1	Important Applications of Semiconductor Devices	572
19.10	Microelectronics	573
19.10.1	Construction of Semiconductor Microelectronic Circuit	573
19.10.2	Fabrication of Thin Film Microelectronic Circuit	574
19.10.3	Brief Description of Some Semiconductor Devices	574
19.10.4	Semiconductor Lasers	575
19.10.5	Materials for Semiconductor Lasers	575
19.11	Semiconductor Crystal Growth	576
19.11.1	Bridgman Method	577
19.11.2	Czochralski Method	577
19.12	Fabrication of a Semiconductor P-N Junction	578
19.13	Transistor Manufacturing Processes	579
19.14	Hall Effect	580
19.14.1	Explanation of the Phenomenon	580
19.14.2	Hall Voltage	580
19.14.3	Significance of Hall Effect, Hall Coefficient etc.	581
19.15	Solved Examples	582
	<i>Review Questions</i>	586
	<i>Numerical Problems</i>	587
20.	DIELECTRIC (OR INSULATING), FERROELECTRIC, PIEZOELECTRIC AND PYROELECTRIC	589—617
20.1	Introduction to Dielectric Materials	589
20.2	Classification of Dielectric (or Insulating) Materials	590
20.3	Main Properties	591

20.4	Dielectric Constant	591
20.4.1	Factors Affecting Dielectric Constant	591
20.5	Dielectric Strength	592
20.5.1	Types of Dielectric Breakdown	593
20.6	Dielectric Loss	593
20.6.1	Factors Affecting Dielectric Loss	594
20.7	Polarization	595
20.7.1	Expression for Polarization under Static Electric Field	595
20.7.2	Measurement of Polarization	596
20.8	Mechanism of Polarization	598
20.8.1	Electronic Polarization	598
20.8.2	Ionic Polarization	599
20.8.3	Orientation (Molecular) Polarization	599
20.8.4	Space Charge (or Interfacial) Polarization	599
20.9	Comparison of Different Polarization Processes	599
20.9.1	Polarizability	600
20.10	Factors Affecting Polarization	600
20.10.1	Time Effects and Relaxation Time	600
20.10.2	Frequency Effects	601
20.11	Spontaneous Polarization	601
20.11.1	Polarization Curve	601
20.11.2	Polarization Hysteresis Loop	602
20.11.3	Salient Features of Spontaneous Polarization	602
20.12	Solid Insulating Materials and Their Applications	602
20.13	Ferroelectric Materials	603
20.14	Barium Titanate : A Ferroelectric Ceramic	604
20.14.1	Effect of Temperature on Structure of BaTiO ₃	604
20.14.2	Modified Barium Titanate	605
20.15	Piezoelectricity	606
20.15.1	Mechanism of Piezoelectricity	607
20.15.2	Inverse Piezoelectric Effect	607
20.15.3	Piezoelectric Materials	607
20.15.4	Electrostriction	608
20.16	Relation between Young's Modulus and Electric Field in Piezoelectric Materials	608
20.17	Lead Zirconate Titanate (PZT): A Piezoelectric Ceramic	610
20.17.1	Different Types of PZTs and Their Uses	610
20.18	Lead Lanthanum Zirconate Titanate (PLZT)	610
20.18.1	General Formula and Hysteresis Loop of PLZT	611
20.19	Pyroelectricity	612
20.19.1	Pyroelectric Effect	612
20.19.2	Pyroelectric Devices	612
20.20	Solved Examples	613
	<i>Review Questions</i>	616
	<i>Numerical Problems</i>	617

21. MAGNETIC MATERIALS: PROPERTIES, BEHAVIOUR AND APPLICATIONS. 618—655

21.1	Origin of Permanent Magnetic Dipole	618
21.1.1	Spinning Electrons Acting as Extremely Small Magnets	618
21.2	Terminologies Defined	619
21.2.1	Relation between Relative Permeability and Magnetic Susceptibility	620
21.3	Classification of Magnetic Materials	622
21.3.1	Distribution of Magnetic Moments	622
21.4	Diamagnetism and Diamagnetic Materials	623
21.4.1	Negative Susceptibility	623
21.5	Paramagnetism and Paramagnetic Materials	623
21.5.1	Rare-earth Based Paramagnetic Salts	624
21.6	Ferromagnetism and Ferromagnetic Materials	624
21.7	Antiferromagnetism and Antiferromagnetic Materials	624
21.7.1	Maximum Susceptibility and Neel Temperature	625
21.8	Ferrimagnetism and Ferrites	625
21.8.1	Properties of Ferrites	626
21.8.2	Applications of Ferrites	626
21.8.3	Soft and Hard Ferrites	626
21.8.4	Spinel, Garnet and Magnetoplumbite	627
21.8.5	Normal and Inverse Spinel	627
21.8.6	Garnets	627
21.8.7	Ferrites in Memory Devices	627
21.9	Curie Temperature	628
21.9.1	Requirement of Higher and Lower Curie Temperature for Different Applications	629
21.10	Laws of Magnetic Materials	629
21.10.1	Effect of Temperature on Magnetic Susceptibility	630
21.11	Magnetization Curve, and Initial and Maximum Permeability	631
21.11.1	Magnetic Hysteresis Loop (or Cycle Magnetization)	631
21.12	Hysteresis and Eddy Current Losses	632
21.12.1	Eddy Current Loss per Unit Volume	632
21.13	Domain Theory	635
21.14	Magnetic Materials	635
21.15	Soft Magnetic Materials	635
21.15.1	Transformer Purpose Sheet Form Magnetic Material	636
21.15.2	Powder Form Magnetic Material	636
21.16	Hard Magnetic Materials	637
21.16.1	Soft Magnetic Materials Versus Hard Magnetic Materials	638
21.17	High Energy (Product) Hard Magnetic Materials (HEHMMs)	638
21.17.1	Samarium-Cobalt Rare Earth	638
21.17.2	Neodymium-Iron-Boron Alloy	639
21.18	Magnetostriction	639
21.18.1	Salient Features of Magnetostriction	640

21.18.2	Mechanism of Magnetostriction	640
21.18.3	Magnetostrictive Materials	641
21.19	Ferromagnetic Anisotropy	641
21.19.1	Anisotropy in Single Crystal	641
21.19.2	Soft and Hard Directions	642
21.19.3	Methods of Inducing Magnetic Anisotropy	642
21.20	Domain Growth and Domain Wall Rotation	643
21.21	Magnetic Storage	644
21.21.1	Magnetic Tapes and Films	644
21.22	Metallic Glasses	644
21.22.1	Interesting Amorphous Material	645
21.22.2	Unusual Properties of Metallic Glasses	645
21.22.3	Materials System and Salient Applications of Metallic Glass	646
21.23	Magnetic Bubbles	647
21.23.1	Working Principle	647
21.23.2	Moving the Magnetic Bubble	647
21.23.3	Information Storage Density	648
21.24	Effects of Alloying Elements on Magnetic Properties	649
21.25	Textured Magnetic Materials	649
21.26	Amorphous (or Oxide) Magnetic Materials	649
21.27	Powder Magnetic Materials	649
21.28	Solved Examples	650
	<i>Review Questions</i>	652
	<i>Numerical Problems</i>	654
22.	SUPERCONDUCTING MATERIALS: PROPERTIES, BEHAVIOUR AND APPLICATIONS	656—676
22.1	Concept of Superconductors	656
22.1.1	Meaning of the Phenomenon of Superconductivity	656
22.2	Properties of Superconductors	657
22.2.1	Meissner Effect	657
22.3	Types of Superconductors	658
22.3.1	Effect of Pressure and Temperature on Superconductivity	659
22.4	Critical Magnetic Field and Critical Temperature	659
22.4.1	Effect of Isotopic Mass on Critical Temperature	659
22.4.2	Silsbee Rule	660
22.4.3	Important Terminologies	661
22.5	Ideal and Hard Superconductors	661
22.6	Mechanism of Superconduction	662
22.6.1	Various Theories of Superconductivity	662
22.7	London's Theory for Type I Superconductors	663
22.8	GLAG Theory for Type II Superconductors	663
22.8.1	Distinguishing Between the Type I and Type II Superconductors	663
22.8.2	Variation of Magnetic Field	664

22.9	BCS Theory	665
22.9.1	Supercurrent	665
22.9.2	Phonon and Photon	665
22.9.3	Electron-Phonon Interaction	665
22.9.4	Reason of Two Electrons Forming a Pair	666
22.9.5	Cause of Resistance for Superconductor being Zero	666
22.9.6	Relationship between Coherence Length and Energy Gap	666
22.9.7	Debye Temperature	667
22.10	Current Applications and Limitations	668
22.10.1	Limitations of Superconductors	668
22.10.2	Likely Futuristic Scenario	668
22.11	Milestones in Research and Development of Superconductors	669
22.11.1	Modern Ceramic Superconductors	669
22.12	Present Scenario of the Main Applications of High Temperature Superconductors	670
22.13	Producing the Superconducting Solenoids and Magnets	671
22.14	MRI for Medical Diagnostics	672
22.14.1	Magnet as a Critical Component	672
22.14.2	Superconducting Magnet	672
22.15	Solved Examples	672
	<i>Review Questions</i>	676
	<i>Numerical Problems</i>	676
23.	THERMAL PROPERTIES AND MATERIALS	677—691
23.1	Thermal Properties	677
23.2	Specific Heat	677
23.3	Thermal Expansion	679
23.3.1	Gruneisen Constant and Coefficient of Linear Expansion	679
23.3.2	Coefficient of Linear Expansion as a Function of Temperature	680
23.3.3	Thermal Elongation of a Rod	680
23.4	Thermal Conductivity	682
23.4.1	Salient Features of Different Materials Regarding Thermal Conductivity	682
23.5	Melting Point	683
23.5.1	Relation between Coefficient of Thermal Expansion and Melting Point	683
23.6	Thermal Stress	683
23.6.1	Thermal Stresses in Bimetallic Strip	684
23.6.2	Warpage	685
23.6.3	Spalling (or Thermal) Cracking	685
23.7	Thermal Fatigue and Thermal Shock	686
23.7.1	Achieving Better Thermal Shock Resistance	686
23.7.2	High Thermal Shock Resistivity Material	686
23.8	Thermal Protection	687
23.8.1	Technique of Reflective Insulation	687
23.9	Thermal Effects	687

23.9.1	Meaning of High and Low Temperatures	688
23.9.2	High Temperature Effects	688
23.9.3	Variation in Ultimate Strength	688
23.9.4	Low Temperature Effects	689
23.10	Effect of Temperature and Time on Structural Changes	690
	<i>Review Questions</i>	690
	<i>Numerical Problems</i>	691
24.	POWDER METALLURGY	692—717
24.1	Introduction	692
24.1.1	Necessity of Powder Metallurgy Methods Over Conventional Production Methods	692
24.2	Operations Involved in Powder Metallurgy	693
24.2.1	Raw Materials, Additives and Lubricants Powder Production	693
24.2.2	Secondary and Other Finishing Operations	694
24.3	Methods of Powder Production	694
24.4	Mechanical (Milling and Grinding) Methods of Powder Production	696
24.4.1	Equipment Used for Mechanical Powder Production	696
24.4.2	Ball Mill	698
24.4.3	Dry and Wet Milling	698
24.5	Chemical Methods of Producing Powder	698
24.6	Thermal Decomposition (or Carbonyl) Method of Powder Production	698
24.6.1	Carbonyl Reactions	699
24.6.2	Specific Applications	699
24.7	Electrolytic Deposition Method	699
24.7.1	Suitable Metals for Producing Powder From Electrolytic Deposition Process	700
24.7.2	Advantages and Disadvantages of Electrolytic Deposition Process	700
24.8	Atomization Method of Powder Production	700
24.8.1	Different Types of Atomization Processes	701
24.8.2	Inert Gas Atomization Process	701
24.8.3	Water Atomization	702
24.9	Powder Conditioning (or Treatment)	703
24.9.1	Characteristics of Metal Powders	704
24.9.2	Influence of Powder Characteristics	705
24.10	Fabrication Methods of Products from Powder	705
24.11	Compaction of Metal Powders	706
24.11.1	Unidirectional Pressing (or Die Compaction) Method	706
24.12	Sintering	707
24.12.1	Sintering Temperature and Sintering Time	707
24.12.2	Different Types of Sintering Process	708
24.12.3	Structure and Property Changes During Sintering	708
24.12.4	Sintering of Blended Powders	709

24.12.5	Furnaces Used for Sintering	709
24.12.6	Post-sintering Operations	710
24.13	Applications of Powder Metallurgy	711
24.14	Advantages and Disadvantages of Powder Metallurgy	712
24.15	Manufacturing of Cemented Carbide by Powder Metallurgy (Sintering) Method	713
24.15.1	Producing Cemented Tungsten Carbide Tipped Tools	714
24.16	Comparison Between Conventional and Powder Metallurgy Methods	714
24.16.1	Comparison Between the Properties of Powder Metallurgy Made Sintered Components And Conventionally Made Solid Components	714
24.17	Recent Advances in Powder Metallurgy	715
24.18	Solved Examples	715
	<i>Review Questions</i>	716
25.	ENGINEERING MATERIALS: FERROUS AND NON-FERROUS METALS AND ALLOYS, AND EFFECTS OF ALLOYING ELEMENTS	718—758
25.1	Iron and Steel Manufacture	718
25.1.1	Manufacturing of Pig Iron	719
25.1.2	Manufacturing of Cast Iron	719
25.1.3	Manufacturing of Steel	719
25.1.4	Manufacturing of Wrought Iron	719
25.2	Classification of Steels and Cast Irons	720
25.2.1	Low-Carbon Steels	720
25.2.2	Medium-Carbon Steels	721
25.2.3	High-Carbon Steels	721
25.2.4	Ultrahigh-Carbon Steel (UHCS)	721
25.2.5	Plain Carbon Commercial Steels	722
25.3	Cast Iron	722
25.3.1	Types of Cast Irons	723
25.4	Grey Cast Iron	723
25.4.1	Mechanical Properties of Grey Cast Iron	723
25.4.2	Factors Affecting the Properties of Grey Cast Iron	723
25.4.3	Microstructure of Cast Iron	724
25.4.4	Effect of Si and Graphitization of CI	724
25.5	Other Cast Irons	725
25.5.1	White Cast Iron	725
25.5.2	Mottled Cast Iron	725
25.5.3	Malleable Cast Iron	725
25.5.4	Spheroidal Graphite (SG) Cast Iron (or Nodular Cast Iron)	725
25.5.5	Inoculated Cast Iron	725
25.5.6	Alloy Cast Iron	726
25.6	Wrought Iron	726
25.7	Alloys and Alloying Elements	727
25.7.1	Purpose Served by Alloying Elements on Steel	727

25.7.2	Austenite Forming and Carbide Forming Alloying Elements	728
25.7.3	Effects of Alloying Elements on Steels	728
25.7.4	Summary of the Effects of Various Alloying Elements on Steel	729
25.8	Alloy Steels	730
25.8.1	Classification of Alloy Steels	730
25.8.2	Low Alloy Steels	731
25.8.3	High Alloy Steels	731
25.9	Stainless Steels (or Corrosion Resistant Steels)	731
25.9.1	Ferritic Stainless Steel	731
25.9.2	Martensitic (Hardenable Alloys) Stainless Steel	731
25.9.4	Salient Features of Different Types of Stainless Steels	732
25.9.5	Applications of Stainless Steels	732
25.10	Marageing Steel	732
25.11	Nickel Alloys	733
25.11.1	Hastelloy : The Nickel-Molybdenum Steel Alloy	733
25.12	Heat Resisting Alloys	735
25.13	Superalloys	736
25.13.1	Types of Superalloys	736
25.14	Cryogenic Steels (or Extremely Low Temperature Purpose Alloys)	737
25.14.1	Ni-based Cryogenic Steels	737
25.15	Tool and Die Steels	738
25.15.1	High Speed Tool Steels	738
25.16	Other Alloy Steels	739
25.16.1	High-strength Low-alloy (HSLA) Steel	739
25.16.2	Microalloyed Steels	739
25.16.3	Free Cutting Steel	739
25.16.4	Wear Resisting Steels	739
25.16.5	Some Common Steel Alloys	740
25.17	Copper	740
25.18	Copper Alloys	741
25.18.1	Brass	741
25.18.2	Bronze	742
25.18.3	Other Copper Alloys	742
25.19	Aluminium	743
25.20	Aluminium Alloys	744
25.21	Magnesium	744
25.21.1	Magnesium Alloys	744
25.22	Various Types of Brass, Bronze, Aluminium and Magnesium Alloys :	
	Their Composition and Applications	745
25.23	Nickel	746
25.23.1	Nickel Alloys	746
25.24	Zinc	747
25.24.1	Zinc Alloys	747

25.25	Titanium	747
25.25.1	Titanium Alloys	747
25.26	Lead and Lead-based Alloys	748
25.26.1	Lead and Lead Alloys as Sheathing Materials	748
25.27	Tin and Tin-based Alloys	748
25.28	Bearing Materials (or Babbits): Their Compositions, Properties and Uses	749
25.29	Fusible Metals and Alloys	749
25.30	Common Non-ferrous Alloys	750
25.31	Properties of Silver, Platinum, Palladium, Rhodium etc.	751
25.32	Solder Materials	752
25.32.1	Soft Solder	753
25.32.2	Hard Solder	753
25.33	Other Non-ferrous Metals	753
25.34	Ni and Si as Sealing Materials	754
25.35	Thermocouple Materials	755
25.36	Metals and Alloys for Nuclear Industry	755
	<i>Review Questions</i>	756
26.	OPTICAL PROPERTIES OF MATERIALS, AND MATERIALS FOR OPTO-ELECTRONIC DEVICES	759—786
26.1	Introduction	759
26.1.1	Important Terminologies Related to Optical Materials	759
26.2	Optical Phenomena	760
26.2.1	Interaction of Light with Solids	761
26.2.2	Types of Optical Materials	761
26.3	Reflection	761
26.4	Refraction	762
26.4.1	Refractive Index	762
26.4.2	Bi-Refringence	763
26.4.3	Relation between Refractive Index and Dielectric Constant	764
26.5	Transmittivity	765
26.6	Scattering	765
26.7	Optical Absorption	765
26.7.1	Capability of a Material to Absorb Light	766
26.7.2	Mechanism of Optical Absorption	766
26.7.3	Absorption Coefficient	767
26.7.4	Factors Affecting the Absorption Coefficient	768
26.7.5	The Absorption Spectra of Materials	770
26.8	Optical Properties of Non-metals	770
26.9	Metals	771
26.10	Optical Properties of Semiconductors	771
26.10.1	Visibility Range of Light Spectrum	771
26.11	Optical Properties of Insulators	772
26.11.1	Optical Absorption in Ionic Crystals	773

26.12	Luminescence	773
26.12.1	Different Types of Luminescence	773
26.12.2	Photo-Luminescence	774
26.12.3	Electro-Luminescence	774
26.13	Opto-Electronic Devices	775
26.14	Solar Cells	775
26.14.1	Working Principle	775
26.14.2	Construction and Working	776
26.14.3	Factors Affecting the Efficiency of Solar Cells	776
26.14.4	Solar Cell Fabrication and Materials	777
26.14.5	Advantages and Limitations of Solar Cells	778
26.14.6	Applications of Solar Cells	778
26.15	Optical Materials in Light Emitting Diodes	778
26.15.1	Construction and Working of LED	779
26.15.2	Advantages, Applications and Specifications of LEDs	779
26.15.3	Applications and Specifications of LEDs	779
26.15.4	Light Emitting Materials	780
26.16	Materials for Optical Fibres	780
26.16.1	Construction	781
26.16.2	Types of Optical Fibres	781
26.16.3	Suitable Materials and their Requirements	782
26.16.4	Advantages and Applications	783
26.16.5	Applications of Optical Fibres	783
26.17	Solved Examples	783
	<i>Review Questions</i>	785
	<i>Numerical Problems</i>	786
	QUICK REVISION DEFINITIONS AND TERMINOLOGIES	787—799
	OBJECTIVE TYPE QUESTIONS	800—841
	REFERENCES	842—843
	SUBJECT INDEX	844—853